




Skoda

VIN:

Essence



Généré le 17/06/2025

Scanne pour obtenir le rapport complet



Kilométrage

✓ Tout a l'air bien



Statut légal

✓ Tout a l'air bien



Domage

✓ Tout a l'air bien



+36

Sources de données

Nous avons vérifié plus de 900 sources de données dans 40 pays



Les partenaires

Ce rapport se base sur

Vol

Le véhicule est-il actuellement signalé comme volé ? A-t-il été volé par le passé ? A-t-il été retrouvé ?



Aucun problème détecté

Nous n'avons trouvé aucune indication démontrant que le véhicule ait été volé.



Note

Bases de données policières. Vérification des véhicules volés effectué dans 10 pays :  +4

Voici ce que nous avons vérifié :



Actuellement déclaré volé

✓ Aucun enregistrement trouvé



Volé par le passé

✓ Aucun enregistrement trouvé

Nous n'avons pas trouvé d'historique de vol pour ce véhicule.

Base de données de la police sur les véhicules volés – **vérification effectuée en :**

 Slovaquie Tchèque Slovénie Roumanie Italie Hongrie Canada Suède Lituanie États-Unis


Kilométrage

Y a-t-il des signes de compteur kilométrique trafiqué ou des différences ?



Note

Dernier kilométrage connu : 114 253 km



Avertissement : ce graphique représente une tendance estimée du kilométrage. Bien qu'il soit basé sur les relevés de kilométrage réels disponibles pour ce véhicule, il y a des manques car toutes les entrées de kilométrage ne sont pas enregistrées de manière uniforme. Pour tenir compte de ces points de données manquants, nous appliquons un modèle d'analyse de données exclusif qui prédit l'évolution probable du kilométrage entre les entrées enregistrées. Cela permet d'obtenir une image plus complète de l'utilisation du véhicule au fil du temps.

Statut légal

Le véhicule a-t-il passé le contrôle technique ? A-t-il été marqué comme mis à la casse ?



Aucun problème détecté

Aucune information sur le statut juridique de ce véhicule n'a été trouvée.

Juridique



Contrôle technique

✓ Aucun enregistrement trouvé

Pas d'enregistrement de contrôle technique trouvé



Épave

✓ Aucun enregistrement trouvé

Rien n'indique que le véhicule a été déclaré comme épave

Dommage

Cette section t'aide à comprendre si le véhicule a été endommagé ou s'il a été expertisé suite à des dommages, ainsi que les estimations de coûts enregistrées (si disponibles).

✓ Aucun problème détecté

Registre des dommages



Des inexactitudes peuvent parfois se produire, surtout lorsqu'on vérifie des véhicules plus anciens. Les ateliers de réparation clandestins peuvent déguiser illégalement les défauts et dommages d'un véhicule. Parfois, même les plaques VIN d'un véhicule peuvent être remplacées. Nous avons diverses méthodes pour détecter ces infractions, mais il est impossible de fournir une garantie à 100%.

Catastrophes naturelles

Le véhicule a-t-il été localisé dans la zone d'une catastrophe naturelle ?

✓ Aucun problème détecté

Le véhicule ne s'est pas trouvé dans la zone d'une catastrophe naturelle

Spécifications et équipement

Quels sont les spécifications et l'équipement connus pour ce véhicule ?

i Note

Vérifiez que les spécifications et l'équipement de ce véhicule correspondent aux déclarations du vendeur.

Identification et spécifications techniques



Marque

Skoda



Type de carrosserie

Liftback



Année du modèle

2016



Déplacement moteur

2l



Puissance moteur

162 kW (217 hp)



Type de carburant

Essence



Type de transmission

Automatique



Type de conduite

Traction



Nombre de portes

4



Position du volant

Volant à gauche



Marché du modèle

Europe



Code du moteur

CHHB



Génération

3. Generation

Équipement

D'origine, sortie d'usine

0A2

4 DOORS

0B3

WHEELBASE

0ES

INSTALLATION DIFFERENTIATION FOR TRANSMISSION
DQ250 -- VEHICLE COMPONENTS --

0K0

WITHOUT ALTERNATIVE DRIVE SYSTEM

0AE

FRONT STABILIZER

0BN

REAR STABILIZER

0FA

STANDARD MANUFACTURING SEQUENCE

0KA

WITHOUT DECALS AND EMBLEMS

0N4

4-LINK REAR SUSPENSION

0TD

FLOOR MATS IN FRONT AND REAR

0Y1

STANDARD CLIMATIC ZONES

1A5

FUEL SYSTEM FOR SI ENGINE

1D0

WITHOUT TRAILER HITCH

1EX

SPECIAL IDENTIFICATION PLATE FOR EC FOR M1 PASSENGER VEHICLE

1JE

REAR SPORTS SHOCK ABSORPTION

1LG

DISK BRAKES IN FRONT

1NL

TRIMS FOR ALLOY WHEELS

1Q0

WITHOUT MASS DAMPER FOR STEERING WHEEL

1SA

WITHOUT ADDITIONAL FRONT UNDERBODY GUARD

1W2

GLOVE COMPARTMENT COOLING SYSTEM

1Y3

ELECTRONIC DIFFERENTIAL LOCK XDS DYNAMIC TRACTION CONTROL

20A

WITHOUT ELECTRIC MOTOR (HYBRID)

2B0

WITHOUT ADDITIONAL EXTERIOR NOISE SUPPRESSION

2H5

DRIVING PROFILE SELECTION AND CONVENTIONAL SHOCK ABSORBER

0P4

EXHAUST TAILPIPE, DOUBLE-FLOW

0VC

INFORMATION KIT IN GERMAN

0YD

WEIGHT RANGE 4 INSTALLATION CONTROL ONLY, NO REQUIREMENT FORECAST

1AZ

ELECTRONIC STABILITY CONTROL (ESC)

1E1

ACTIVATED CARBON CANISTER

1G8

BREAKDOWN KIT

1KT

DISK BRAKES IN REAR (GEOMET D)

1N7

DYNAMIC STEERING

1PF

STANDARD WHEEL BOLTS

1S3

TOOL KIT

1U8

WITHOUT FOLDING TABLE ON FRONT SEAT BACKREST

1X0

FRONT WHEEL DRIVE

1Z0

INITIAL STANDARD FUEL FILLING

2A0

WITHOUT DELIVERY EQUIPMENT

2G7

FILLER NECK MODULE 1 WITH INSERT

2JK

SPORTS BUMPERS

2KW

LABELS/PLATES IN GERMAN, FRENCH, AND DUTCH

2W6

FUEL FILLER CAP

2ZS

LEATHER-WRAPPED MULTIFUNCTION STEERING WHEEL WITH TIPTRONIC

3CA

WITHOUT PARTITION

3FA

WITHOUT ROOF INSERT (STANDARD ROOF)

3GA

WITHOUT CARGO AREA

3J4

HEAD RESTRAINTS FOR FRONT SEATS

3LE

DOOR AND SIDE TRIM PANEL

3NU

REAR SEAT BENCH UNSPLIT, BACKREST SPLIT FOLDING WITH CENTER ARMREST

3S0

WITHOUT ROOF RAILS/ROOF LOAD RACK

3U1

FOLDING TRUNK COVER

3X0

WITHOUT LOAD-THROUGH HATCH

4A3

SEAT HEATER FOR FRONT SEATS SEPARATELY CONTROLLED

4F2

CENTRAL LOCKING SYSTEM "KEYLESS ENTRY"

4KF

SIDE WINDOWS IN HEAT-INSULATING GLASS, FROM B-PILLAR AND REAR WINDOW DARK TINTED

4LC

2V5

FRESH AIR INTAKE SYSTEM WITH COMBINATIONFILTER

2WA

WITHOUT ADDITIONAL TIRES

3B4

CHILD SEAT ANCHOR FOR CHILD SEAT SYSTEM ISOFIX

3D7

CENTER CONSOLE

3G0

WITHOUT CHILD SEAT ANCHOR FRONT (ISOFIX)

3H0

WITHOUT BACKREST RELEASE FOR FRONT SEATS

3L4

POWER SEAT ADJUSTMENT FOR BOTH FRONT SEATS, DRIVER SEAT WITH MEMORY FEATURE

3N1

STORAGE COMPARTMENTS IN TRUNK

3QC

3-POINT SEAT BELTS IN FRONT

3T2

THREE REAR HEAD RESTRAINTS

3W7

ACOUSTICS PACKAGE "EXTRA"

3Y0

WITHOUT ROLL-UP SUNSHADE

4E2

TAILGATE/TRUNK LID RELEASE FROM INSIDE (ELECTRICALLY)

4GF

WINDSHIELD IN HEAT-INSULATING GLASS

4L6

BREAKAWAY INTERIOR REARVIEW MIRROR, AUTO-DIMMING

4P3

CONTROLS FOR RADIO AND TELEPHONE

4R4

POWER WINDOWS WITH COMFORT OPERATION AND CIRCUIT BREAKER

4X3

SIDE AIRBAG IN FRONT, WITH CURTAIN AIRBAG

5C0

WITHOUT SPECIAL BODY MEASURES

5K7

TRANSPORT PROTECTION FILM (MINIMUM PROTECTION) WITH ADDITIONAL TRANSPORT PROTECTION MEASURES

5RQ

RIGHT EXTERIOR MIRROR, CONVEX

5XB

SUN VISORS WITH MIRROR AND AIRBAG LABEL ON FRONT PASSENGER SIDE, AND AIRBAG LABEL ON SUN VISOR

6FM

COMPONENTS WITH SPECIAL SURFACE APPEARANCE

6M0

WITHOUT TIE DOWN STRAPS/NET/POCKET

6PC

HAND BRAKE LEVER HANDLE IN LEATHER

6R1

LEATHERETTE GEARSHIFT BOOT

6T2

INTERIOR LIGHT IN FOOTWELL IN FRONT AND REAR

7AS

ANTI-THEFT ALARM SYSTEM, INTERIOR MONITORING, BACKUP HORN, AND TOWING PROTECTION

7E0

WITHOUT HEAT ACCUMULATOR/AUXILIARY HEATER

REAR FLOOR PANEL MODULE, TYPE 4

4UP

DRIVER AND FRONT PASSENGER AIRBAG WITH KNEE AIRBAG AND FRONT PASSENGER AIRBAG DEACTIVATION

4ZD

BLACK MOLDINGS

5D1

CARRIER FREQUENCY 433.92 MHZ-434.42 MHZ

5ML

DECORATIVE INSERTS

5SJ

LEFT EXTERIOR MIRROR, CONVEX

6E3

CENTER ARMREST IN FRONT

6K3

FORWARD COLLISION WARNING INCL. AUTONOMOUS EMERGENCY BRAKING, FOR ADAPTIVE CRUISE CONTROL "LOW"

6N0

WITHOUT MUD FLAP

6Q2

LEATHER GEARSHIFT KNOB/HANDLE

6SD

LUGGAGE COMPARTMENT FLOOR COVERING IN NEEDLE-PUNCHED NONWOVEN (DIMENSIONALLY STABLE)

6XL

EXTERIOR MIRRORS WITH MEMORY FEATURE, AUTO-DIMMING, POWER-FOLDING/ADJUSTABLE/HEATED

7B2

12-VOLT SOCKET IN LUGGAGE BOOT

7G0

WITHOUT PREPARATION FOR VTS (VEHICLE TRACKING SYSTEM)

7K1

DIRECT TIRE PRESSURE MONITORING SYSTEM

7LM

VEHICLE CLASS DIFFERENTIATION -5E0-

7MM

EMISSION STANDARD EU6 PLUS

7P1

POWER-ADJUSTABLE LUMBAR SUPPORT IN FRONTSEATS

7UF

NAVIGATION SYSTEM - STANDARD

7X1

PARK DISTANCE CONTROL

8G0

WITHOUT LIGHT CONTROL

8IP

GAS-DISCHARGE HEADLAMPS WITH VARIABLE LIGHT DISTRIBUTION

8M0

WITHOUT REAR WINDOW WIPER AND WASHER SYSTEM

8Q5

HEADLIGHT RANGE ADJUSTMENT, AUTOMATIC/DYNAMIC, WITH CORNERING LIGHT (AFS 1)

8S6

2 READING LIGHTS IN FRONT

8T3

ADAPTIVE CRUISE CONTROL

8W1

WASHER FLUID LEVEL INDICATOR

8X1

HEADLAMP WASHER SYSTEM

8Z5

NOT HOT COUNTRY

9AK

7L6

START/STOP SYSTEM WITH REGENERATIVE BRAKING

7M3

SCUFF PLATES IN DOOR APERTURES

7N2

SPECTACLE STORAGE COMPARTMENT/BRACKET

7RE

SD CARD (EUROPE)

7W0

WITHOUT EXTENDED SAFETY SYSTEM

7Y4

LANE KEEPING SYSTEM

8GU

ALTERNATOR 140 A

8K3

SEPARATE DAYTIME RUNNING LIGHTS WITH AUTOMATIC HEADLAMP ACTIVATION AND COMING HOME FEATURE

8N6

WINDSHIELD WIPER INTERMITTENT CONTROL WITH LIGHT/RAIN SENSOR

8QL

KEY FOR LOCKING SYSTEM WITH REMOTE CONTROL

8SK

LED TAIL LAMP ASSEMBLY

8TB

REAR FOG LAMP

8WB

FRONT FOG LAMPS

8Y1

TWO-TONE HORN

8ZH

ANTENNA FOR AM/FM RECEPTION, "DIVERSITY"

9D0

CLIMATRONIC WITH IMPACT PRESSURE CONTROL,
CFC-FREE

9E3

LUGGAGE COMPARTMENT LIGHTING

9J1

SUPERTONE SYSTEM AND TONE SEQUENCE
CONTROL

9M9

FUEL-FIRED PARKING HEATER WITH RADIO REMOTE
CONTROL

9S6

MULTI-FUNCTION DISPLAY/ON-BOARD
COMPUTER"COLOUR"

9TG

ADDITIONAL WARNING LIGHTS (DOOR AREA)
INFRONT

9VS

SOUND PACKAGE "BRANDED"

9Z0

OPERATING VOLTAGE 12 V

A64

CATEGORY 4

AV1

DRIVING ON THE RIGHT

B0A

COMPONENT PARTS SET WITHOUT COUNTRY-
SPECIFIC BUILDING REGULATION

CW6

ALLOY WHEELS 7.5J X 19

E2D

SPECIAL EDITION

EF1

ECO FUNCTION

EM0

WITHOUT DRIVER ALERT SYSTEM

ES0

WITHOUT PREPARATION FOR TWO-WAY RADIO
INSTALLATION

9HA

WITHOUT ADDITIONAL MALFUNCTION DISPLAY

9JD

SMOKER'S PACKAGE, ASHTRAY IN FRONT

9P5

VISUAL AND ACOUSTIC SEAT BELT REMINDER,
ELECTRIC CONTACT

9T1

HEATED WASHER NOZZLES IN FRONT

9U1

BRAKE PAD WEAR INDICATOR

9WT

MIRRORLINK

9ZE

COMFORT TELEPHONE SYSTEM

A8F

SPORTS EQUIPMENT

B01

TYPE APPROVAL COUNTRY GERMANY

C00

OPERATING PERMIT, INITIAL REGISTRATION

D60

4-CYLINDER SI ENGINE 2.0 L/162 KW (16V) TURBO FSI,
HOMOGENEOUS, BASE ENGINE IS
T61/TW6/TP6/T1P/TA9,TL6/TG6/TA2/TI6

EA0

WITHOUT FOLLOW-ON WARRANTY

ELO

WITHOUT ONLINE SERVICE

ER1

REGIONAL CODE " ECE " FOR RADIO

FOA

WITHOUT VEHICLE INLET

FB0

STANDARD PAINT COATING

G07

SHOCK ABSORPTION IN FRONT

GM1

STANDARD ELECTRONIC ENGINE SOUND

I8E

STANDARD RADIO (GEN2)

K8B

NOTCHBACK

KK1

REFRIGERANT R134A

L17

SUSPENSION RANGE 17 INSTALLATION CONTROL ONLY, NO REQUIREMENT FORECAST

ND0

WITHOUT ADAPTER

QE1

STORAGE COMPARTMENT PACKAGE 1

QH1

VOICE CONTROL

QJ9

CHROME PACKAGE

QQ0

WITHOUT ADD. LIGHTS (INTERIOR LIGHTING)

QV3

DIGITAL RADIO RECEPTION

TP6

4-CYLINDER SI ENGINE 2.0 L UNIT 06K.A

UG1

HILL START ASSIST

UI4

ELECTRIC INTERFACE FOR EXTERNAL USE, AUX-IN JACK, USB (IPOD-CAPABLE)

NO SPECIAL PURPOSE VEHICLE, STANDARD EQUIPMENT

FM0

BASIC EQUIPMENT VARIANT

G1A

6-SPEED AUTOMATIC TRANSMISSION

HI5

TIRES 225/35 R19 88Y

J2D

BATTERY 380 A (68 AH)

KA0

WITHOUT CAMERA SYSTEMS/ACCIDENT SENSORS

LOL

LEFT-HAND DRIVE

N1A

SEAT TRIM COVERS IN LEATHER

Q4H

SPORTS COMFORT SEATS IN FRONT

QG1

SERVICE INTERVAL PROLONGATION

QI6

SERVICE INDICATOR 30 000 KM OR 2 YEARS (VARIABLE)

QK1

WITH MULTIFUNCTION CAMERA

QR8

WITHOUT DYNAMIC ROAD SIGN DISPLAY

SI1

PRICE SUPPORT

U5A

INSTRUMENT CLUSTER, KM/H SPEEDOMETER

UH0

PARKING BRAKE

UK3

MECHANICAL REAR SEAT RELEASE

V1P

TIRE SUPPLIERS FOR EU COUNTRIES

VLO

STANDARD PEDESTRIAN PROTECTION MEASURES

VF1

PEDAL CLUSTER

X0A

EQUIPMENT OPTIONS SUBSET FOR GERMANY



+36

Sources de données

Nous avons vérifié plus de 900 sources de données dans **40 pays**



Les partenaires

Ce rapport se base sur